

# berkeley heights, NJ

Based on berkeley heights

Provider Number	Nursing Home Name	Street
315009	RUNNELLS SPECIALIZED HOSPITAL	40 WATCHUNG WAY
315009	RUNNELLS SPECIALIZED HOSPITAL	40 WATCHUNG WAY
315009	RUNNELLS SPECIALIZED HOSPITAL	40 WATCHUNG WAY
315009	RUNNELLS SPECIALIZED HOSPITAL	40 WATCHUNG WAY
315009	RUNNELLS SPECIALIZED HOSPITAL	40 WATCHUNG WAY
315009	RUNNELLS SPECIALIZED HOSPITAL	40 WATCHUNG WAY
315009	RUNNELLS SPECIALIZED HOSPITAL	40 WATCHUNG WAY

# berkeley heights, NJ

Based on berkeley heights

City	State	Zip Code	Phone	Survey Date	Date of Correction
BERKELEY HEIGHTS	NJ	07922	(908) 771-5807	04/04/2008	04/25/2008
BERKELEY HEIGHTS	NJ	07922	(908) 771-5807	04/04/2008	04/14/2008
BERKELEY HEIGHTS	NJ	07922	(908) 771-5807	04/04/2008	04/23/2008
BERKELEY HEIGHTS	NJ	07922	(908) 771-5807	05/01/2009	05/01/2009
BERKELEY HEIGHTS	NJ	07922	(908) 771-5807	05/01/2009	05/07/2009
BERKELEY HEIGHTS	NJ	07922	(908) 771-5807	05/01/2009	05/01/2009
BERKELEY HEIGHTS	NJ	07922	(908) 771-5807	05/01/2009	06/15/2009

# berkeley heights, NJ

Based on berkeley heights

Deficiency Type	Deficiency Category
Fire Safety	Vertical Openings Deficiencies
Fire Safety	Smoke Compartmentation and Control Deficiencies
Fire Safety	Exits and Egress Deficiencies
Fire Safety	Hazardous Area Deficiencies
Fire Safety	Automatic Sprinkler Systems Deficiencies
Fire Safety	Automatic Sprinkler Systems Deficiencies
Fire Safety	Smoking Regulations Deficiencies

# berkeley heights, NJ

Based on berkeley heights

Deficiency	Scope	Level of Harm
exit doors that are held open by devices that will automatically close on the activation of a fire alarm or smoke detectors.	Isolated	Minimal harm or potential for actual harm
smoke barrier doors that can resist smoke for at least 20 minutes.	Pattern	Minimal harm or potential for actual harm
exits that are accessible at all times.	Widespread	Potential for minimal harm
construction that can resist fire for one hour or an approved fire extinguishing system.	Isolated	Minimal harm or potential for actual harm
an approved automatic sprinkler system connected to the fire alarm system.	Isolated	Minimal harm or potential for actual harm
automatic sprinkler systems that have been maintained in working order.	Isolated	Minimal harm or potential for actual harm
posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Isolated	Minimal harm or potential for actual harm

# berkeley heights, NJ

Based on berkeley heights

315009	RUNNELLS SPECIALIZED HOSPITAL	40 WATCHUNG WAY
315009	RUNNELLS SPECIALIZED HOSPITAL	40 WATCHUNG WAY
315009	RUNNELLS SPECIALIZED HOSPITAL	40 WATCHUNG WAY
315009	RUNNELLS SPECIALIZED HOSPITAL	40 WATCHUNG WAY
315195	BERKELEY HEIGHTS NURSING AND REHABILITATION CENTER	35 COTTAGE STREET
315195	BERKELEY HEIGHTS NURSING AND REHABILITATION CENTER	35 COTTAGE STREET
315474	BERKELEY MEADOWS	311 SPRINGFIELD AVENUE
315474	BERKELEY MEADOWS	311 SPRINGFIELD AVENUE
315474	BERKELEY MEADOWS	311 SPRINGFIELD AVENUE
315474	BERKELEY MEADOWS	311 SPRINGFIELD AVENUE

# berkeley heights, NJ

Based on berkeley heights

BERKELEY HEIGHTS	NJ	07922	(908) 771-5807	05/01/2009	06/15/2009
BERKELEY HEIGHTS	NJ	07922	(908) 771-5807	06/24/2010	06/25/2010
BERKELEY HEIGHTS	NJ	07922	(908) 771-5807	06/24/2010	07/31/2010
BERKELEY HEIGHTS	NJ	07922	(908) 771-5807	06/24/2010	07/13/2010
BERKELEY HEIGHTS	NJ	07922	(908) 464-0048	08/12/2009	08/24/2009
BERKELEY HEIGHTS	NJ	07922	(908) 464-0048	08/12/2009	08/24/2009
BERKELEY HEIGHTS	NJ	07922	(908) 464-9260	07/02/2008	01/01/1900
BERKELEY HEIGHTS	NJ	07922	(908) 464-9260	07/02/2008	01/01/1900
BERKELEY HEIGHTS	NJ	07922	(908) 464-9260	07/02/2008	01/01/1900
BERKELEY HEIGHTS	NJ	07922	(908) 464-9260	08/05/2009	08/31/2009

# berkeley heights, NJ

Based on berkeley heights

Fire Safety

Building Service Equipment Deficiencies

Fire Safety

Corridor Walls and Doors Deficiencies

Fire Safety

Fire Alarm Systems Deficiencies

Fire Safety

Automatic Sprinkler Systems Deficiencies

Fire Safety

Hazardous Area Deficiencies

Fire Safety

Automatic Sprinkler Systems Deficiencies

Fire Safety

Building Construction Deficiencies

Fire Safety

Exits and Egress Deficiencies

Fire Safety

Exits and Egress Deficiencies

Fire Safety

Vertical Openings Deficiencies

# berkeley heights, NJ

Based on berkeley heights

properly protected cooking facilities.	Isolated	Minimal harm or potential for actual harm
corridor and hallway doors that block smoke.	Pattern	Minimal harm or potential for actual harm
an approved installation, maintenance and testing program for fire alarm systems.	Isolated	Minimal harm or potential for actual harm
automatic sprinkler systems that have been maintained in working order.	Widespread	Minimal harm or potential for actual harm
construction that can resist fire for one hour or an approved fire extinguishing system.	Isolated	Minimal harm or potential for actual harm
portable fire extinguishers.	Isolated	Minimal harm or potential for actual harm
approved construction type or materials.	Pattern	Potential for minimal harm
corridors or aisles that are unobstructed and are at least 8 feet in width.	Pattern	Potential for minimal harm
resident room doors of proper design and width.	Pattern	Potential for minimal harm
exit doors that are held open by devices that will automatically close on the activation of a fire alarm or smoke detectors.	Isolated	Minimal harm or potential for actual harm



# berkeley heights, NJ

Based on berkeley heights

# berkeley heights, NJ

Based on berkeley heights

# berkeley heights, NJ

Based on berkeley heights

# berkeley heights, NJ

Based on berkeley heights

alarm or smoke detectors.